

C5RA Visit Process Flowchart (Cobra)


as of November 17, 2000

LEGEND

- S = Schedule
- P = Plan
- R = Prepare
- C = Procedure Management
- V = Execution (Visit)
- F = Follow up/Analyze
- M = Manage

Filenames:

- Section 1 - 2000-1117c1.pdq
- Section 2 - 2000-1117c2.pdq
- Section 3 - 2000-1117c3.pdq



* Goal is to have no more than 4 C5RA Visits scheduled at the same time

** 2 Wks - CG, DD, DDG, LHA, LHD
 1 Wk - All Others
 No Phase II - MCM, MHC

